



Customer: Sample Report  
 Customer Rep: Maintenance Manager

Location: **Chiller #3**  
 Component: **Main Disconnect**  
 Fault Area: **A-phase line side**



IR Info	Value
Date	2008-6-20
Label	Value
Max:Temp	259.82
P02:Temp	146.84

Rating /Temp Rise	
F	
<b>Minor</b>	<b>: 1-18</b>
<b>Alert</b>	<b>:19-36</b>
<b>Serious</b>	<b>:37-54</b>
<b>Critical</b>	<b>:&gt;55</b>

RATING / Temp Rise : Critical / 113F

**REPAIR INSTRUCTIONS:**

Replace conductors and clean all other areas of contact before installation of new wires.